


FIG. 1


09531850-032100

FIG. 2A



09531860.03239ax


MULTICHIP CERAMIC PACKAGE 28



R = measured
resistance
during temperature
ramp-up and ramp-down

FIG. 2B


Defective part with intermittent short (W1008)



09531850.032100

FIG. 3A
DKT 481-R3

Part W1008 after removal of short




— Series 1

09531860 : 032400

FIG. 3B

PKT 481-AB

Defective epoxy contact on part (W1020)




— Series 1

00534860.032100

FIG. 4

PKT 481-RB

Part W1020 after repair of defective epoxy contact



— Series 1

FIG. 5

09531850.032100

DKT 481-RB